

## Appendix D

APPENDIX D  
COLOR PHOTOGRAPHS



Building #2 with Freon column and reboiler in the foreground, fin coolers on the roof and the 1200 ft<sup>2</sup> heat exchanger on the left.



Rigging for removal of piping to the fin coolers.





Arrangement during cleaning activities  
(note miscellaneous piping in decontamination pan).



Typical triple rinsing of miscellaneous piping.





Typical dismantling of piping and equipment.



Collection of decontamination rinsate.



Tanks #8 and #9.



Inside of Tank #8 (also typical of #9).





Inside of Tank #9 (also typical of #8).



Two (2) 1650 ft<sup>2</sup> heat exchangers.



Removal of boiler exhaust stack with crane.





Triple rinsing of exchanger pit.



Demolition of exchanger pit.